

List of Monuments and Structures at Risk



*Image: Detail of the Prior's House, Remains of Beauvale Priory (Greasley);
image opposite: Gatepiers at Gatehouse Lodges (Drakeholes, Wiseton).*

Listed Structures and Monuments at Risk in Ashfield

Locality	Risk Level	Name	Description	Reasons for Risk
Annesley	1A	Terrace to South West of Annesley Hall	Late 17th century garden terrace with double stairway. Brick with Ashlar dressings and balustrade. Upper stage has a pair of wrought iron gates.	Badly overgrown - balustrades are missing from central double stairs. The retaining wall is being pushed forward & timber props are used to stabilise. Iron gates are damaged by vegetation growth.
Bagthorpe	3A	Wansley Hall	Ruined remains of medieval manor house some of which date to the 13th century. Coursed and squared rubble of dressed stone and brick, with remains of internal timber framing.	Heavy vegetation growth around the site. Ruin has a tarpaulin cover over one section.
Kirkby in Ashfield	3A	Garden Wall, 12-16 Chapel Street	Late 18th century garden wall of coursed and squared rubble with half round coping.	Large cracks and collapsed stonework to western side.
Skegby	3A	Walled Garden to North of Dalesforth House	Buttressed brick garden wall with flat slab coping.	Poor condition.

Listed Structures and Monuments at Risk in Bassetlaw

Locality	Risk Level	Name	Description	Reasons for Risk
Blyth	3A	Memorial to Joseph Dymond in Churchyard 45m South of the South Aisle	Late 18th century ashlar obelisk memorial.	Large cracks, very worn stonework, vegetation is growing out of the base.
Blyth	3A	Entrance Gateway formerly to Blyth Hall	Gate piers dating to circa 1770 of ashlar and wrought iron.	Stone damage around all metal mounting joints.
Blyth	3A	Milestone 90m South of Ivy Cottages	Late 18th century triangular ashlar milestone.	Poor condition.
Church Laneham	1A	Wall at Manor Farmhouse	Low red brick wall with ashlar coping surmounted by iron railings with decorative finials	

Clarborough	1A	Pair of Chest Tombs at the Church of St John the Baptist	Mid 19th century ashlar chest tombs enclosed by iron railings, with decorated traceried panels.	Overgrown; the railings are collapsing.
Cottam	3A	Font beside the South Porch of the Church of Holy Trinity	Octagonal 14th century ashlar font bowl carried on an octagonal stem.	Removed from its base. Becoming green.
Cuckney	3A	Walls, Railings and Sluice Gates at Cuckney Mill	18th century dam of ashlar and coursed rubble with iron railings and sluices.	Ironwork is corroding. Vegetation growth around the sluices.
Darlton	3A	Chest Tomb 1842 to Thomas Newstead, Church of St Giles	One of three ashlar chest tombs enclosed in a rectangular iron compound.	Railings are split and generally in bad repair. The tomb is covered in ivy.
Darlton	3A	Chest Tomb of 1845 to Mary Ann Newstead, Church of St Giles	One of three ashlar chest tombs enclosed in a rectangular iron compound.	Railings are split and generally in bad repair. The tomb is covered in ivy.
Darlton	3A	Chest Tomb 1818 to Mary (?), Church of St Giles	One of three ashlar chest tombs enclosed in a rectangular iron compound.	Railings are split and in generally bad repair. The tomb is covered in ivy.
Drakeholes	3A	Gatepiers at Gatehouse Lodges	Four round stone gatepiers with incised decoration and gadrooned caps.	Overgrown at time of survey.
Drakeholes	1A	Icehouse at the Gatehouse Lodges	An icehouse dating to the early 19th century in the grounds of the Gatehouse Lodges to Wiseton Hall.	Unused; the site is overgrown to an extent that the structure is no longer accessible.
Dunham	3A	Headstone 1731 to Mary Bacon, Church of St Oswald	One of a group of three 18 th century ashlar headstones.	Very eroded and difficult to read.
Dunham	3A	Headstone 1738 to Robert Wills, Church of St Oswald	One of a group of three 18 th century ashlar headstones.	Very eroded, inscription is becoming illegible.
Dunham	3A	Headstone 1729 to Mary Bo....ll, Church of St Oswald	One of a group of three 18 th century ashlar headstones.	Very eroded, inscription is becoming illegible. High amount of lichen cover may be speeding up erosion.
East Retford	1A	Gateposts to South at Bolham Hall	Set of 18 th century gateposts with pineapple finials.	Replaced – state and location of the originals are unknown.
East Retford	3A	Gateposts to North at Bolham Hall	Set of 18 th century gateposts with pineapple finials.	Poor condition.
Haughton	3A	Church of St James	Ruined church dating to the early 12 th century,	Problems with vegetation growth. The corner of the

			built of ashlar, dressed rubble and coursed rubble. Remains include that of the nave, chancel and north chantry.	west wall is collapsing and needs re-mortaring in position.
Misson	3A	Boundary Wall 25m long at Northfield House	19 th century cast iron spearhead railings on a dwarf wall.	Damage to sections of the railings; some repointing required to wall.
Misson	3A	Boundary Wall 75m long at Holly House	19 th century brick boundary wall with stone coping.	Poor pointing and eroding brickwork.
Misterton	3A	Access Bridge at Pumping Engine Houses	Access bridge dated 1803 and built of brick with stone coping.	The structure is covered in vegetation and the water channel entrance is barely visible.
Rampton	3A	Gateway and Walls from Manor Farm to Church of All Saints	Heavily decorated gateway and walls dating to the mid 16 th century. Built of red brick, ashlar and terracotta.	Very bad condition of masonry; there is collapsing with clear gaps right through, and vegetation growth from the gateway. Overall condition is between poor and very bad.
Rockley	3A	Icehouse at Rockley House Cottage	Icehouse with a late 18 th century interior and a 19 th century exterior, built in red brick with a pantile roof.	(no update since 1991; highlighted in previous survey as being in poor condition)
Serlby	3A	Arch at Serlby Park	Early 18 th century archway of dressed coursed rubble and brick.	Mass of climbing vegetation.
Serlby	1A	Garden Seat in Serlby Park	Late 18 th century garden seat of red brick, ashlar and stucco, with a pantile roof and coped parapet.	Collapse of north pier; cracks at south pier indicate that it is close to collapse too. This may be affected by subsidence due to the Harworth colliery.
Shireoaks	3A	Ha-Ha at Shireoaks Hall	Early 18 th century Ha-Ha of coursed squared rubble with ashlar coping.	Heavy vegetation cover and collapse of stonework.
South Wheatley	1A	Church of St Helen Remains	Remains of parish church dating to the 12 th and 15 th century. Built of ashlar and coursed rubble the tower and chancel arch remain.	Vegetation growth has taken over the structure. There are trees growing close to the base of the tower, and there is evidence of recently fallen masonry.
Sutton	3A	Gate Piers and Gates to Sutton Manor Grounds	Late 18 th century gate piers and gates of ashlar and wood.	Some spalling stonework and poor pointing.
Wallingwells	3A	Walled Garden at Wallingwells Hall	Walled garden of coursed rubble with quoins and ashlar coping.	Poor condition.

Wallingwells	1A	Walls and Pavilions at Wallingwells Castle Garden	Mid 18 th century quadrangular garden walls with four pavilions at the angles, designed in a style of a castle. Built of coursed rubble with ashlar dressings.	Overall in a poor condition.
Welbeck Abbey	3A	Grotto	Double roomed grotto of rough hewn rock, dating to the mid 19 th century.	Very overgrown and fenced off (for Health&Safety reasons?) Some of the iron structure is rusting at the base of steps.
Welbeck Abbey	3A	Wall and Gateway to North of the Abbey	Mid 19 th century wall and gateway of ashlar and iron.	Damage and loss of coping to wall as well as some eroded stonework. There are damp issue on the house side of the wall.
Wiseton	3A	Lady's Bridge, Chesterfield Canal	Late 18 th century ornamental canal bridge. Rendered brick with ashlar dressings and 19 th century, cast iron railings.	Corroding railings, excessive ivy growth and loss of render. One pier has collapsed.
Wiseton	1A	Icehouse at Wiseton Hall	An ice house dating to about 1800. Built in brick, partly rendered. The interior has a circular, saucer domed ice chamber.	Unused and neglected. The icehouse has trees growing out of the roof splitting the structure and the brickwork has partially collapsed.
Worksop	3A	Chimney at Bracebridge Pumping Station	A tall Romanesque style chimney of three stages, of brick and ashlar.	Poor pointing and vegetation growth.
Worksop	3A	Cloister Wall at Church of SS Cuthbert and Mary	Remains of 12th century cloister wall with round headed and four centred arched doorways.	Lots of vegetation is growing out of the ruin and there are trees growing very close to base. Some signs of recent stone fall.
Worksop		Icehouse to Rear of Gateford Farmhouse	Icehouse of the late 18th century built of coursed squared rubble and brick with ashlar dressings.	Unused and neglected. There are saplings growing out of the mount affecting the masonry.
Worksop	3A	Drive Walls and Gate Piers at Worksop Manor	Two 18th century rubble and ashlar boundary walls flanking the driveway with rusticated gatepiers.	Large sections are in a poor condition and there has been some substantial collapse along the drive walls.

Listed Structures and Monuments at Risk in Broxtowe

Locality	Risk Level	Name	Description	Reasons for Risk
Awsorth	3A	Bennerley Viaduct	Wrought iron railway viaduct built in 1877. This building utilises a system of prefabricated lightweight construction patented by J. Warren and W. T. Manzoni in 1848.	Redundant with signs of vandalism.
Beeston	3A	Platform Shelter adjoining Station	Long wooden platform shelter dating to 1848, originally constructed at Southwell Station transferred here 1871. Wood and cast iron with C20 asphalt roof covering.	Zero glazing to shelter roof. Urgent need of replacement. Otherwise structurally sound.
Bramcote	3A	Tombs at the Tower of Church of St Michael	Group of four chest tombs at the base of the tower, two to the east and two to the south.	Poor condition and signs of vandalism.
Greasley	1A	South Cloister Wall Part of the Ruins of Beauvale Priory	Carthusian priory remains including chamfered pointed door and square opening. Interior has 2 pointed barrel vaulted rooms and remains of spiral stair shaft.	In urgent need of consolidation.
Greasley	1A	Church South Wall Part of the Ruins of Beauvale Priory	South wall of church at remains of Carthusian priory dating to 1343. Has blocked doorway, doorway to cloister and remains of 15th century double lancet window.	In urgent need of consolidation.
Greasley	3A	Wall at Greasley Castle Farmhouse	Coursed rubble boundary wall with ramped slab coping	Poor pointing.
Moorgreen	3a	Gates at 54 Moorgreen	Wrought iron gates dating to 1709, formerly at the Collins Almshouses Nottingham. Resited in 1973.	Some areas of excessive corrosion.
Nuthall	3A	Lake Bridge	Ornamental bridge in gothic style of circa 1759, probably by Thomas Wright for Sir Charles Sedley. Rockfaced and moulded ashlar.	Much fallen stonework, some of it more recent.
Nuthall	3A	Summerhouse at The Yews	Gothic Summerhouse dating to 1759, probably	Roof has gone at the apex. Ashlar steps are

			by Thomas Wright. Formerly located in the garden of Nuthall Temple (demolished 1926). Coursed and squared rubble and brick with ashlar dressings and a plain tile roof.	subsiding. Vegetation growth from parapet and turret.
Trowell	3A	Swansea Bridge on the Nottingham Canal	Canal overbridge of circa 1795 of dressed stone and ashlar. Curved parapet walls have half-round coping and small terminal piers.	Large crack on the side, strapping to underside of arch not recent. Boarded up from the south side.

Listed Structures and Monuments at Risk in Gedling

Locality	Risk Level	Name	Description	Reasons for Risk
Bestwood Park	3A	Walled Garden and Gateway at Bestwood Park	Garden walls and gateway dated 1862. Built in brick with stone dressings and a set of wrought iron gates by S.S. Teulon for the 10th Duke of St. Albans.	Pointing issues and spalling brickwork
Burton Joyce	3A	Spire Top beside Church of St Helen	14th century octagonal spiretop, approx. two metres high.	Eroding brickwork in places.
Newstead	3A	Railway Overbridge	Cast iron and rockfaced ashlar bridge of circa 1875. Iron balustrade and segmental headed arch.	Vegetation growth. Some parts of the moulding on the railings are missing. Metalwork needs re-painting.
Newstead Park	1A	Cascade and Pool 20m North of Garden Wall at Newstead Abbey	Cascade and oval pool dating to the early 18th century. Built of coursed, squared rubble and concrete. Has a stepped cascade with ramped flanking walls and mask spout.	Very overgrown at the time of survey.
Newstead Park	3A	Male Satyr Statue 100m East of Newstead Abbey	Ashlar and lead statue on pedestal of a male satyr figure with a goat dating to the early 18th century. Probably by John Nost.	Goat part of statue has been stolen.
Newstead Park	3A	Cannon Fort	Mock fort dated 1750. Built for the fifth Lord Byron who enjoyed staging mock naval battles. Of coursed and squared rubble and ashlar.	Three sections of battlements have fallen over the edge. Paving slabs are missing from walkway. There is Graffiti on the walls.

Newstead Park	3A	West Gable of former Augustinian Priory Church (Remains)	Late 13th century west gable of the former Priory church attached to the West of Newstead Abbey.	The stonework is in fragile condition.
Papplewick	3A	Sundial 16m North of Papplewick Lodge	Sundial dated 1819. It has a square ashlar base, with verse and text inscriptions. There is a square baluster shaped stem with a bronze dial.	Problems due to weathering. There is a large crack in the side.
Papplewick	3A	Chest Tomb 8m South of Church of Saint James	Ashlar chest tomb dated 1695 with moulded base and corners. Panels on long sides have ornamented borders and crossed fleur-de-lys shafts. Ends have panels containing a stag's head and a rosette.	Subsidence in the area is causing the top of the tomb to move. There is ivy growing over and into the tomb.
Papplewick	3A	Walled Kitchen Garden 100m North of Papplewick Hall	Rectangular mid 18 th century walled garden, built in brick with flat ashlar copings. The gate and freestanding wall have square piers with flat caps. The north and south sides have central gateways.	The wall is in a very varied condition; there is some damage to brick and pointing from climbing plants & the removal of lean-to buildings, other areas of the wall are in good condition

Listed Structures and Monuments at Risk in Mansfield

Locality	Risk Level	Name	Description	Reasons for Risk
Mansfield	3A	Tomb 90m NE of Cemetery Chapel at Mansfield Cemetery	Tomb of circa 1857. Rock-faced stone with ashlar dressings and stone slab roof in a Classical Revival style	Overall poor condition.
Mansfield	3A	Gate Piers at Berryhill Hall	Square rusticated ashlar gate piers of circa 1770.	Poor condition.
Mansfield Woodhouse	3A	Boundary Wall to the SW, the South and the SE of the Manor House	Boundary wall of coursed rubble.	Poor pointing and missing stones.
Mansfield Woodhouse	3A	Boundary Wall adjoining Stables at Debdale Hall	Early 18th century curved boundary wall with half round coping.	Coping stones missing, pointing is extremely weathered.
Mansfield Woodhouse	1A	Icehouse at Debdale Hall	An early 18th century icehouse built of dressed stone with	This structure no longer has a roof and is extremely eroded with

			ashlar dressings; square in plan.	foliage now growing out of it.
Mansfield Woodhouse	3A	Chest Tomb 10m South of Chancel at St Edmund's Church	Ashlar chest tomb dated 1772 with moulded panel sides and top.	Overgrown with ivy.
Mansfield Woodhouse	3A	Boundary Wall to 11 Church Street	18th century boundary wall and gateways of coursed squared rubble.	Wall has been badly repointed using ribbon pointing. The door surround is badly eroded and needs recording.
Mansfield Woodhouse	3A	Headstone 10m South of Chancel at St Edmund's Church	Headstone dated 1694 with scrolled shaped top.	Stone has fallen over onto face and needs righting.

Listed Structures and Monuments at Risk in Newark and Sherwood

Locality	Risk Level	Name	Description	Reasons for Risk
Blidworth	1A	Friar Tuck's Well	Early 19th century well head of ashlar and red brick. Six stepped water course above ashlar trough.	Collapse of lower steps of the water course. There is a submerged section that can only be seen when the pond dries out.
Budby	1A	Garden Urn at Castle View	Ashlar Garden Urn dating to the mid 19th century.	Missing.
Carlton on Trent	3A	Curved Boundary Wall and Gates to the North of Carlton Hall	18th century boundary wall built of brick with ramped terra cotta and ashlar copings. At the main opening there is a pair of ornamental wrought iron gates. The west side carries plain iron railings.	Many holes in brickwork and deep gaps in-between; the spalling is especially bad to the NE corner. Some leaning.
Clipstone	1A	King John's Palace	Remains of a hunting lodge of circa 1164, with alterations and additions up to the 16th century. Rubblecore only remaining.	In a deteriorating condition; there is evidence of recently fallen masonry. Some vegetation growth.
East Stoke	1A	Decorative Chains before Monument at the Church of St Oswald	Monument to the Right Honourable Julian Baron Pauncefote, the first British Ambassador to the U.S.A. Dated 1902 and of ashlar, bronze and iron.	The decorative iron chains are now missing from the monument.
East Stoke	3A	Northernmost Chest Tomb and Next Southern-	Part of a group of four ashlar chest tombs of the late 18th century.	Bad condition with collapsed panels and vegetation growing inside.

		most Chest Tomb at Church of St Oswald	Has moulded corners in the form of pilasters.	
East Stoke	3A	Footbridge over School Lane in the Grounds of Stoke Hall	Tall arched, red brick footbridge with some ashlar work, dating to the early 19th century.	Some areas of damp and crumbled brickwork. The exterior layer of bricks are spalled up to about the 15th course.
Edwinstowe	3A	Monument to a Horse	Monument to a horse dated 1834 consisting of a Doric column with capital and ball finial.	Located within woodland; vegetation growth is an issue and the general condition of the structure is deteriorating
Egmanton	3A	Sundial 5m South of the Church of St Mary	18th century ashlar sundial on a stepped base.	There is cracked masonry and the base is uneven causing the shaft to lean.
Epperstone	3A	Pinfold	Rectangular pinfold in coursed rubble of the late 18th century. It has rounded coping and a wooden gateway.	The wall is collapsed in the NW corner and many areas are in need of repointing. Ivy growth causes also problems.
Grassthorpe	1A	Pinfold	Village pinfold dating to the 19th century. Built of brick with triangular brick coping. There are two square brick piers with dressed stone caps and also an inscribed stone relating to the Diamond Jubilee 1897.	Vegetation growth inside and on the walls. The brickwork is cracked and crumbled with eroded pointing leaving deep gaps.
Halam	3A	Footbridge attached to Halam Mill	Concrete and ashlar foot bridge with single red brick arch to the rear.	Poor condition.
Newark on Trent	3A	Railings and Gate to left of 26 and 28	Early 19th century cast iron spearhead railings and gate.	Covered in ivy and other vegetation. A trunk is forcing itself between the gate and railing. Some lost spearheads.
North Muskham	3A	Railings and Gate at North Road House	Dwarf wall and railings with timber gate dating to the early 19th century. Built of brick with stone coping and cast and wrought iron railings..	Rusting iron work, wooden gate rotten and damaged. The 20th century brickwork is still in fair condition.
Norwood Park	3A	Former Kitchen Garden Walls 150m NE of Norwood Park	Former kitchen garden walls dating to the mid 18th century. Built of red brick with flat stone coping.	Poor pointing and worn and perished brickwork. The small lean-to buildings to the rear are also in poor condition.
Norwood Park	3A	Ha-ha 75m South and West of Norwood Park	Mid 18th and early 19th century Ha-ha. Brick wall with coping and iron gates.	Wall is now only 50% present compared to what is recorded on the listing, the rest is just a ditch line.

Ollerton	3A	Boundary Wall at Ollerton Hall	Boundary wall dating to the early 19th century. Built of brick it has ashlar caps with ramped brick and ashlar coping.	There are gaps in pointing and perished brickwork.
Ossington	1A	Wall and Gate at Church of the Holy Rood	19th century brick boundary wall with wrought iron gate and overthrow. The wall has half round brick coping and stone gate piers. The overthrow has a lamp.	The actual gate to the church is in fair condition, the rest of the wall is dilapidated. The coping stones are missing and some wall sections are collapsed and/or covered by vegetation.
Ossington	1A	Sundial 5m South of Church of the Holy Rood	Ashlar sundial dated 1812 by Arthur Buckle. Vase Baluster stem on moulded base and bronze dial.	Stolen, only the moulded round base remains.
Ossington	3A	Monumental Well at Ossington Hall	Octagonal monumental well dated 1877 as a memorial to Edward Denison (died 1870). Ashlar with terracotta decorative panels designed by John Birnie Philip, it is in a classical style.	Weathering and deterioration of the ashlar. The Iron finial is heavily rusted. Heavy vegetation growth.
Oxton	3A	Chest Tomb of Robert Sherbrooke in former Woodyard of Oxton Hall	Ashlar chest tomb dated 1710 with cast iron railings set on an ashlar plinth extending around the tomb.	Railings are damaged and there is heavy vegetation growth. The inscription is fading.
Perlethorpe	1A	South Lamp at West Gate at Church of St John	Gas street lamp of circa 1861. Made of cast and sheet iron with a rendered brick plinth.	Heavily corroded and fallen into two pieces on the floor by the gateway.
Rufford	3A	Fence in front of the West Gate at Rufford Abbey	Fence dating to the mid 19th century in the Jacobean Revival style. Probably by A. Salvin.	Damaged; missing balusters and chain.
Rufford	3A	Garden Urn 25m East of Rufford Abbey	Ashlar garden urn on a rendered brick plinth. It is vase shaped with an octagonal body flanked by mermaids. Probably removed from the parapet of Rufford Abbey.	Although now repaired back to one piece this is badly eroded.
Rufford	1A	Garden Urn 110 metres North West of Rufford Abbey	Ashlar garden urn on a rendered brick plinth. It is vase shaped with an octagonal body flanked by mermaids. Probably removed from the parapet of Rufford Abbey.	Very poor condition; split into three sections. Sculpted vase and mermaids are badly eroded. Poor brickwork and loss of render at plinth and vegetation growth.

Rufford	3A	Guard Stones at West Gate at Rufford Abbey	Two guard stones with domed tops.	Eroding stonework.
Rufford	3A	Minor Icehouse at Rufford Abbey	A single bay icehouse built in the early 19th century. Round in plan with a flat floor and domed ceiling.	Unused and overgrown. The brickwork around the entrance has deteriorated and is in poor condition
Southwell	3A	Gateway and Railings at Brackenhurst Hall	Gateway and wrought iron railings of circa 1900 in late 17th century style. Dwarf walls are of ashlar.	Eroding stonework.
Southwell	1A	Summerhouse at the Rear of Dunham House	Gothick Summerhouse of the early 19th century. Timber and brick with a plain tile roof. Has leaded lights and traceried doors. The brick wall to the rear has remains of shellwork.	Complete collapse; the walls are left to a height of two foot in places, only one stack of brickwork remains to roof height. Roof tiles and timbers are lying in piles of rubble. The site is very overgrown.
Southwell	3A	Wall and Gatepiers at Honing House	Boundary wall and gatepiers dating to the mid 19th century, built of brick with stone dressings. It has a cast iron gate.	Poor brickwork from the base up to the middle with a lot of perished brickwork.
Southwell	3A	Boundary wall to former House of Correction	Boundary wall to former House of Correction dated 1808. It is built of brick with a flat stone coping and has tapered pyramidal-topped buttresses. Approx. eighty metres long.	Vegetation growth and poor pointing.
Southwell	3A	Wall and Railings at The Hollies	Boundary wall and gatepiers dating to the mid 19th century, built of brick with stone dressings. It has a cast iron gate.	Perishing brickwork at the lower courses.
Southwell	3A	Wall and Gatepiers at Rampton Prebend	Boundary wall and gatepiers of red brick and ashlar dating to the early 19th century. It has a small wrought iron gate.	Poor brickwork from the base to approx. ten courses up.
Southwell	1A	Milestone to Left of Carriage Arch at Saracen's Head Hotel	Milestone dating to the late 18th century. Inscription now partly illegible, showing distances to London and Mansfield.	Inscription is badly eroded.
Syerston	1A	Curved Wall at Syerston Hall	Curved red brick wall dating to the late 18th century.	Spalling brickwork and poor pointing.

Thoresby Park	3A	Pierrepoint Bridge	Ashlar road bridge dating to the late 18th century. It has a moulded soffit and parapet and a plain string course. The east side has a low parapet with fragments of a former balustrade.	There is significant damage to the SE wall and loss of the coping. Still structurally sound enough to be used as vehicle bridge by the estate.
Thoresby Park	1A	Icehouse on Island at East End of Lake	Mid 19th century icehouse on a L-Plan, with a ramped entrance. Built in brick.	Located within the deer park. Not identifiable, appears to be within heavy vegetation and boggy ground.
Thoresby Park	3A	Icehouse 500 Metres SE of Thoresby Hall	Mid 18 th century icehouse with barrel vaulted chamber. Built in dressed stone and brick.	Located within the deer park; brickwork is in poor state of repair.
Thoresby Park	1A	Sundial 150m South of Thoresby Hall	Mid 18 th century ashlar sundial by Thomas Wright. Baluster stem with bronze dial.	Missing from the location recorded.
Thorney	1A	Square Headed Lancel at Church of St Helen, Part of the Ruins of Old Church	Square headed lancet window at Church of St Helen forming part of the ruins of old church.	Collapse.
Thorney	3A	Arched Triple Lancel Window at Church of St Helen	Arched triple lancet window at the Church of St Helen, part of a group of ruins of the old church.	Heavy ivy coverage.
Upton	1A	Pump at Town Farmhouse	19 th century lead water pump with timber case and straight iron handle. Below this is a stone drip trough.	Pump destroyed. Case is smashed and pipes are bent.
Westhorpe	3A	Pump at 40 & 42 Westhorpe	Pump cased in wood dating to the mid 19 th century.	Pump damaged and signs of rot to casing.
Winkburn	3A	Icehouse in Winkburn Park	A red brick icehouse with domed roof and central doorway, dating from the mid 19th century.	No access; highlighted in previous surveys as being in a poor condition.

Listed Structures and Monuments at Risk in Rushcliffe

Locality	Risk Level	Name	Description	Reasons for Risk
Bingham	3A	Wall at 7 Church Str.	Late 18th century brick and mud boundary wall.	Poor condition.

Bunny	1A	Wall around Bunny Park	Large brick boundary wall with decorative gateways enclosing Bunny Park	Very bad condition, collapsed in places. Loss of coping and vegetation growth, the fly is tipping at various sites.
Car Colston	3A	Garden Wall at The Old Hall	Mid 17th century garden and boundary wall with dentillated cornice. Brick with Ashlar dressings and timber gateways.	Severe spalling at the base.
Colston Bassett	3A	Remains of Church of St Mary	Ruined church dating back to the 12th century, though predominantly of the 14th century. Built of ashlar and rubble.	Roof removed in 1892 by Church Commissioners. Has recently had stabilisation work completed under the supervision of English Heritage. This needs careful management in the future.
Colston Bassett	3A	Headstones to Mary and Thomas Church, Church of St Mary	Headstone to Mary Church dated 1757 & headstone to Thomas Church dated 1798	Poor condition.
Cotgrave	3A	Chest Tomb in churchyard of Church of All Saints	Early 19th century ashlar chest tomb with highly decorative panels.	Heavy vegetation and damaged masonry.
East Bridgford	3A	Garden Wall at The Hill	Brick garden wall with buttresses dating to 1792 with gateway with wrought iron gate.	Root damage and perished brickwork /pointing are making the wall unstable. The buttressing is being undercut.
East Bridgford	1A	Wall to South at Manor House	19th century brick boundary wall with slab coping and segmental headed gateway with ornate iron gate.	Overall in a bad condition.
East Leake	3a	Water House	Early 18th century water house designed by Sir Thomas Parkyns of Bunny Hall. Red brick with blue brick chequering. The roof is pantile with coped gables.	Almost completely obscured by the brambles, which are lifting the slates. The brickwork of the coped gables is in poor condition.
Flintham	3A	Wall at Church of St Augustine	Brick and rubble boundary wall with ashlar dressings and coping. Gateway has brick piers with plain iron gates and lamp bracket.	Eroding, bowing and overgrown.
Flintham Hall Park	3A	Garden Walls adjoining the Aviaries	Mid 19th century brick garden walls and aviaries with hipped	Spalling brickwork.

			slate roofs. Aviaries have projecting, canted two storey structure with pigeonholes.	
Granby	3A	Grave Slab mid C18, Church of All Saints	Mid 18th century limestone grave slab.	Heavily eroded.
Hawksworth	3A	Wall at Yew Tree Farmhouse	Early 19th century mud wall with pantile coping.	Poor condition.
Holme Pierrepont	3A	Memorial Late C18 to ?, Church of St Edmund	Late 18th century ashlar memorial with decorative urn.	The decorative urn is removed from the top of the monument and missing.
Holme Pierrepont	3A	Memorial 1802 to Francis Dort de le Borde, Church of St Edmund	Ashlar and slate memorial dated 1802. Chest with scroll moulding topped by a decorative urn.	Substantial crack and damage to masonry, vegetation growth.
Kingston on Soar	1A	River Soar (Kegworth Deep Lock)	Late 18th century pound lock. Built of ashlar, iron, wood and brick with two sets of gates.	This lock is redundant and now filled in and overgrown.
Kinoulton	3A	Collection of Headstones at Site of St Wilfreds Church	Group of 34 headstones, mainly of the 18th century. They are mainly of slate in rectangular shape.	Some stones are fallen, some are cracked and damaged. The site is becoming overgrown. Many structures are leaning, possibly due to ground movement.
Langar	3A	Gateway and Walls to Enclosure South of Langar Hall	18th century brick walls with rusticated 17th century ashlar gatepiers.	Spalling stonework and eroded pointing.
Langar	3A	Chest Tomb to Crosland Family, Church of St Andrew	Chest tomb dating to 1790 with broad squared vase corners.	Overgrown and panels damaged.
Newton	3A	Windmill	Early 19th century red brick base of a post mill. Buttressed two storey structure with segmental headed openings.	In a derelict condition; various repairs needed.
Orston	3A	Gate Piers at Orston Hall	Late 18th century, rusticated gatepiers of ashlar.	Right pier top missing; weathering at base.
Plumtree	3A	Gateway and Wall to The Old Rectory	Early 19th century gateway and wall of red brick and ashlar. Walls are curved with a large wooden gate in the centre.	Bricks missing, largely eroded, large gaps in pointing.
Radcliffe on Trent	3A	Headstones to Joseph and Edward Watts and to John	Flat slate headstone to Joseph and Edward Watts, dated 1759 & and flat slate	Poor condition.

		Graves, Church of St Mary	headstone to John Graves, dated 1791.	
Rough Hill	3A	Old Water House, Gotham Lane	Pyramidal brick roofed waterhouse dating to the early 18 th century.	Unused and neglected.
Ruddington	3A	Walls, Railings and Gate at Adard Print and Stationary Cupboard	Red brick dwarf wall, piers and railings with gateways outside the Ruddington Free School dating to 1875.	Render has collapsed exposing brickwork. Poor pointing and missing or perished bricks. One gate has been removed.
Screveton	3A	Wall at Church of St Wilfrid	Mid 18th century brick boundary wall.	Pointing is poor and there is some spalling.
Screveton	3A	Sundial at the Church of St Wilfrid	Ashlar and bronze sundial dating to 1732.	Sundial element now missing, stonework is in fair condition.
Shelton	3A	Icehouse at Manor Farmhouse	Late 18th century icehouse built of brick. It consists of a round chamber with a shallow dome of 3m in diameter.	No update since 2000 due to access problems. Highlighted in previous surveys as being in poor condition.
Shelton	3A	Pump at Manor Farmhouse	Mid 19th century lead water pump in wood casing.	Poor condition.
Stanford on Soar	1A	Stanford Bridge	Late 18th century brick packhorse bridge of a single low wide arch.	Damage to north parapet while the south parapet has been demolished. Poor pointing.
Stanford on Soar	1A	Urn to West of Penguin Pool in the Grounds of Stanford Hall	Ornamental Urn	Missing.
West Leake	1A	Ashlar Coffin in Churchyard of Church of St Helena	Ashlar chest tomb dated 1731. Chamfered plinth with moulded cornice and inscribed slate plaque.	Poor condition.